

# 1985 Cessna Citation S/II

N550SG s/n S550-0070

FLINN

AVIATION



[www.FlinnAviation.com](http://www.FlinnAviation.com)

512-615-3334

[Tom@FlinnAviation.com](mailto:Tom@FlinnAviation.com)

1985 S/II -70

## NOTABLE FEATURES

- Keith Freon Air Conditioning
- Thrust Reversers
- Upgraded Avionics Garmin 750/530
- B&D Cabin Info Display
- Gill Lead Acid Battery
- Sierra Quick Release Nose Radome
- Recognition Lights
- Precise Flight Pulse Lights
- Quick Donning O2 Masks
- Belted, Flushing Enclosed Lav
- Enrolled on Bacon Low-Utilization Maintenance Program

## INTERIOR

- 8-Place executive interior with forward 2-place divan, mid cabin 4-place club group, and 2-forward facing seats aft.
- Seats in Tan leather with Cream headliner and Sandstone carpet. Maple Birdseye cabinetry.
- Deluxe galley with hot & cold MAPCO, bar, ice chest, and forward left-side storage area.
- Forward and aft sliding doors.
- Aft belted, flushing lav.

## AIRFRAME

Total Time Since New 8,837.9 Hours (6/1/2023)  
Cycles Since New 5,989 Landings

## ENGINES

Pratt & Whitney JT15D-4  
3,500 Hour TBO

### Eng #1 S/N PCE-102083

Total Time Since New 8,459.8 Hours  
Total Cycles Since New 5,627 Cycles  
Time Since Overhaul 2,632.0 Hours  
Time Since Hot Section 905.0 Hours

### Eng #2 S/N PCE-102096

Total Time Since New 8,773.9 Hours  
Total Cycles Since New 5,865 Cycles  
Time Since Overhaul 1,709.0 Hours  
Time Since Hot Section 13.0 Hours

## AVIONICS

- Avionics Package: Honeywell FZ-500 IFCS/Pro Line II
- AP/FD: Honeywell SPZ-500 IFCS Single Cue
- Multifunction Display: Garmin 750
- GPS/Nav/Comm: Garmin 530
- CVR: Fairchild GA100
- DME: Dual Collins DME-42
- ELT: Artex 406-1
- Air Data: IS&S Air Data System with RVSM
- Stormscope: BFGoodrich WX-12
- TCAS I: BFGoodrich TCAS-791
- Transponder: Dual Collins TDR-90
- Weather Radar: Primus 300SL color

## EXTERIOR

Overall Matterhorn White with Black, Yellow, and Platinum stripes in custom paint scheme.

## MAINTENANCE SUMMARY

<u>Inspection</u>	<u>C/W</u>	<u>Due</u>
Phase 12 Mo	10/2022	10/2023
Phase 24 Mo	10/2022	10/2024
Phase 36 Mo	5/2023	5/2026
Phase 48 Mo	9/2020	9/2024
Phase 60 Mo	4/2020	4/2025
Phase 72 Mo	3/2023	3/2029
Phase 96 Mo	2/2022	2/2030
Phase 144 Mo	10/2019	10/2031
#1 Overhaul	6,206 Hr	9,706 Hr
#1 Hot Section	7,933 Hr	9,733 Hr
#2 Overhaul	7,129 Hr	10,629 Hr
#2 Hot Section	8,825 Hr	10,625 Hr

*Aircraft subject to prior sale/removal from market. These specifications are for introductory purposes only and are in no way a warranty from Broker/Agent/Owner of the aircraft on the validity of the information. Purchaser should rely on their own inspection and verify the above information.*

1985 S/II -70



[www.FlinnAviation.com](http://www.FlinnAviation.com)

512-615-3334

[Tom@FlinnAviation.com](mailto:Tom@FlinnAviation.com)

1985 S/II -70



1985 S/II -70



[www.FlinnAviation.com](http://www.FlinnAviation.com)

512-615-3334

[Tom@FlinnAviation.com](mailto:Tom@FlinnAviation.com)